

- RUNOFF FROM MASONRY & SEALANT -



BEFORE

AFTER



During construction stage, masonry work leads to concrete stains that are very hard to remove. Curtain wall contractors usually scrap off concrete with a blade risking scratching the glass panels.

During the building lifespan, streaks appear on curtain wall fronts.

This can be due to sealant bleeding, dirt accumulation or silicate carried by rain. When rain water drains off we observe an unaesthetic deposit formation.

Solution : RENUGLASS

RENU-GLASS is a patented PH Neutral product developed in collaboration with Glass manufacturer Glaverbel (Now AGC).

RENU-GLASS is a blend of rare earth able to restore any pyrolytic glass to its original condition without damaging its original characteristics.